

RFWV2.E123755 - Electrical Quick-connect Terminals - Component

Note: We are enhancing our systems and you may notice duplicate entries/missing/outdated data. During this interim period, please contact our Customer Service at <https://www.ul.com/about/locations>.

Electrical Quick-connect Terminals - Component

INARCA SPA

Via Ca'zusto 35

Vigodarzere, Pd 35010 Italy

E123755

Marking: Company name or trademark  ,  ,  inarca , model designation, and the Recognized Component Mark 

Note: For additional marking information, refer to the [Guide Information Page](#).

Component, Non-insulated Quick-Connect Connectors for copper alloy tabs, Model(s): 0010915201

Component, Non-insulated quick-connect copper alloy tabs, Model(s): 0011546001, 0011546201

Insulating Housing, Model(s): 0854005700, 0854026700, 0854029700, 0854030700, 0854036700, 0854163700, 0854242700, 0854283700, 0854287700, 0855005700, 0855026700, 0855029700, 0855030700, 0855036700, 0855163700, 0855242700, 0855283700, 0855287700, 0856313700, 0862324700, 0862339700, 0863242700, 0863283700, 0864005700, 0864029700, 0864030700, 0864036700, 0864163700, 0864242700, 0864283700, 0864287700, 5450343700, 5452076700, 5452127700, 5452128700, 5452129700, 5452130700, 5452131700, 5452132700, 5452133700, 5552127700, 5552128700, 5552129700, 5552130700, 5552131700, 5552132700, 5552133700, 6352076700, 6352127700, 6352128700, 6352129700, 6352130700, 6352131700, 6352132700, 6352133700, 6352178700, 6450343700, 6452076700, 6452127700, 6452128700, 6452129700, 6452130700, 6452131700, 6452132700, 6452133700, 6452138700

Non-insulated quick-connect connectors for copper alloy tabs, Model(s): 0011779001, 0011779101, 0011780001, 0011780101, 0011781001, 0011781101, 0011782001, 0011782101, 0011783001, 0011783101, 0011854001, 0011854101, 0011886201, 0011887201, 0211351127, 0211352127

Non-insulated Quick-Connect Connectors for copper alloy tabs, Model(s): 0011555001, 0011555101, 0011556001, 0011556101, 0011864201, 0011865201, 0011896201, 0911864001, 0911865001, 0911896001

Non-insulated quick-connect connectors for steel tabs, Model(s): 0211886121, 0211887121

Quick connect connectors, Model(s): 0010101001, 0010101201, 0010129001, 0010129201, 0010246201, 0010375201, 0010381201, 0010616001, 0010616201, 0010629001, 0010629201, 0010656201, 0010765201, 0010820201, 0010937201, 0010984201, 0011061201, 0011076201, 0011077201, 0011111201, 0011112201, 0011239201, 0011240201, 0011241201, 0011242201, 0011253201, 0011322001, 0011322201, 0011331001, 0011331101, 0011332001, 0011332101, 0011348001, 0011348201, 0011349201, 0011351001, 0011351201, 0011352001, 0011352201, 0011363001, 0011363101, 0011364001, 0011364201, 0011365001, 0011365101, 0011365201, 0011396101, 0011396201, 0011397101, 0011397201, 0011398101, 0011398201, 0011406001, 0011406101, 0011407001, 0011407101, 0011408201, 0011409201, 0011410201, 0011415101, 0011416101, 0011418101, 0011419101, 0011444101, 0011453001, 0011453101, 0011454101, 0011455101, 0011458101, 0011459101, 0011496001, 0011496201, 0011522001, 0011522101, 0011539001, 0011539201, 0011608001, 0011608201, 0011609001, 0011609201, 0011819201, 0011818201, 0211602121, 0211348121, 0211322121, 0211608127, 0211819121, 0211818121, 0911364001, 0911365001, 0911415001, 0911416001, 0911496001

Last Updated on 2022-08-09

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL Solutions' Follow - Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL Solutions' Follow - Up Service. Always look for the Mark on the product.

UL Solutions permits the reproduction of the material contained in Product iQ subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from Product iQ with permission from UL Solutions" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "©2022 UL LLC."

RFWV7.E123755 - Electrical Quick-connect Terminals Certified for Canada

Note: We are enhancing our systems and you may notice duplicate entries/missing/outdated data. During this interim period, please contact our Customer Service at <https://www.ul.com/about/locations>.

Electrical Quick-connect Terminals Certified for Canada

INARCA SPA

Via Ca'zusto 35
Vigodarzere, Pd 35010 Italy

E123755

Insulating Housing, Model(s): 6352178700

Non-insulated quick-connect connectors for copper alloy tabs, Model(s): 0011886201, 0011887201

Non-insulated quick-connect connectors for steel tabs, Model(s): 0211886121, 0211887121

Quick connect connectors, Model(s): 0011819201, 0011818201, 0211819121, 0211818121

Last Updated on 2022-08-09

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL Solutions' Follow - Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL Solutions' Follow - Up Service. Always look for the Mark on the product.

UL Solutions permits the reproduction of the material contained in Product iQ subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from Product iQ with permission from UL Solutions" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "©2022 UL LLC."

RFWV8.E123755 - Electrical Quick-connect Terminals Certified for Canada - Component

Note: We are enhancing our systems and you may notice duplicate entries/missing/outdated data. During this interim period, please contact our Customer Service at <https://www.ul.com/about/locations>.

Electrical Quick-connect Terminals Certified for Canada - Component

INARCA SPA

Via Ca'zusto 35

Vigodarzere, Pd 35010 Italy

E123755

Marking: Company name or trademark  ,  ,  inarca , model designation, and the Recognized Component Mark for Canada 

Note: For additional marking information, refer to the [Guide Information Page](#).

Component, Non-insulated Quick-Connect Connectors for copper alloy tabs, Model(s): 0010915201

Component, Non-insulated quick-connect copper alloy tabs, Model(s): 0011546001, 0011546201

Insulating Housing, Model(s): 0854005700, 0854026700, 0854029700, 0854030700, 0854036700, 0854163700, 0854242700, 0854283700, 0854287700, 0855005700, 0855026700, 0855029700, 0855030700, 0855036700, 0855163700, 0855242700, 0855283700, 0855287700, 0856313700, 0862324700, 0862339700, 0863242700, 0863283700, 0864005700, 0864029700, 0864030700, 0864036700, 0864163700, 0864242700, 0864283700, 0864287700, 5450343700, 5452076700, 5452127700, 5452128700, 5452129700, 5452130700, 5452131700, 5452132700, 5452133700, 5552127700, 5552128700, 5552129700, 5552130700, 5552131700, 5552132700, 5552133700, 6352076700, 6352127700, 6352128700, 6352129700, 6352130700, 6352131700, 6352132700, 6352133700, 6450343700, 6452076700, 6452127700, 6452128700, 6452129700, 6452130700, 6452131700, 6452132700, 6452133700, 6452138700

Non-insulated quick-connect connectors for copper alloy tabs, Model(s): 0011779001, 0011779101, 0011780001, 0011780101, 0011781001, 0011781101, 0011782001, 0011782101, 0011783001, 0011783101, 0011854001, 0011854101, 0211351127, 0211352127

Non-insulated Quick-Connect Connectors for copper alloy tabs, Model(s): 0011555001, 0011555101, 0011556001, 0011556101, 0011864201, 0011865201, 0011896201, 0911864001, 0911865001, 0911896001

Quick connect connectors, Model(s): 0010101001, 0010101201, 0010129001, 0010129201, 0010246201, 0010375201, 0010381201, 0010616001, 0010616201, 0010629001, 0010629201, 0010656201, 0010765201, 0010820201, 0010937201, 0010984201, 0011061201, 0011076201, 0011077201, 0011111201, 0011112201, 0011239201, 0011240201, 0011241201, 0011242201, 0011253201, 0011322001, 0011322201, 0011331001, 0011331101, 0011332001, 0011332101, 0011348001, 0011348201, 0011349201, 0011351001, 0011351201, 0011352001, 0011352201, 0011363001, 0011363101, 0011364001, 0011364201, 0011365001, 0011365101, 0011365201, 0011396101, 0011396201, 0011397101, 0011397201, 0011398101, 0011398201, 0011406001, 0011406101, 0011407001, 0011407101, 0011408201, 0011409201, 0011410201, 0011415101, 0011416101, 0011418101, 0011419101, 0011444101, 0011453001, 0011453101, 0011454101, 0011455101, 0011458101, 0011459101, 0011496001, 0011496201, 0011522001, 0011522101, 0011539001, 0011539201, 0011608001, 0011608201, 0011609001, 0011609201, 0211602121, 0211348121, 0211322121, 0211608127, 0911364001, 0911365001, 0911415001, 0911416001, 0911496001

Last Updated on 2022-08-09

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL Solutions' Follow - Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL Solutions' Follow - Up Service. Always look for the Mark on the product.

UL Solutions permits the reproduction of the material contained in Product iQ subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from Product iQ with permission from UL Solutions" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "©2022 UL LLC."